

| Document ID | Attributes | Activity Type | Access Control |
|-------------|-----------------------------------|-------------------------------------------|------------------------|
| 2004934 | | | UCTL(Uncontrolled) |
| 2004769 | | | UCTL(Uncontrolled) |
| 2004709 | | | UCTL(Uncontrolled) |
| 2004626 | | | UCTL(Uncontrolled) |
| 2004470 | | | UCTL(Uncontrolled) |
| 2004471 | | | UCTL(Uncontrolled) |
| 2004625 | | | UCTL(Uncontrolled) |
| 2004362 | | | UCTL(Uncontrolled) |
| 956510 | | | UCTL(Uncontrolled) |
| 956478 | | | UCTL(Uncontrolled) |
| 956479 | | | UCTL(Uncontrolled) |
| 975123 | Administrative RecordPublished | | UCTL(Uncontrolled) |
| 955176 | Administrative RecordPublished | Explanation Of Significant Differences | UCTL(Uncontrolled) |
| 2004206 | | | UCTL(Uncontrolled) |
| 2004138 | | | UCTL(Uncontrolled) |
| 2004136 | Administrative RecordPublished | | UCTL(Uncontrolled) |
| 2003929 | Administrative RecordPublished | | UCTL(Uncontrolled) |
| 969608 | Administrative RecordPublished | FIVE-YEAR REVIEW | UCTL(Uncontrolled) |

| Document Date | Title | File Size (KB) | Page Count |
|---------------|---------------------------------------------------------------------------------------------------------------------------------|----------------|------------|
| 12/07/2022 | U.S. EPA LETTER RE: NOTICE OF RPM CHANGE | 205 | 1 |
| 09/27/2022 | U.S. EPA EMAIL RE: RESPONSE TO REQUEST FOR EXTENSION | 252 | 1 |
| 09/15/2022 | GHD LETTER RE: SAAG REQUEST FOR EXTENSION ON FYR TASKS | 128 | 2 |
| 08/22/2022 | MDH - BUNKER LAKE BOULEVARD STUDY - DEEP GROUNDWATER RESULTS | 2,236 | 55 |
| 07/06/2022 | U.S. EPA LETTER RE: RESPONSE TO SAAG COMMENTS ON FIVE YEAR REPORT | 272 | 3 |
| 06/30/2022 | GHD LETTER RE: RESPONSE TO EPA FOR GROUNDWATER STUDY | 199 | 2 |
| 06/28/2022 | MDH - BUNKER LAKE BOULEVARD STUDY - GROUNDWATER RESULTS | 3,200 | 108 |
| 06/01/2022 | U.S. EPA LETTER RE: 1,4-DIOXANE AND PFAS IN THE VICINITY OF SITE | 124 | 2 |
| 06/01/2022 | SF 135 - 1953-2014 - SITE SPECIFIC REMEDIAL ACTION FILES WITH COMPLETED RODS (PARTIAL SEMS) [PT-412-2022-1067] | 612 | 41 |
| 05/17/2022 | SF 135 - 1964-2009 - SITE SPECIFIC REMEDIAL ACTION FILES WITH COMPLETED RODS (PARTIAL SEMS) [PT-412-2022-1014] | 556 | 41 |
| 05/17/2022 | SF 135 - 1966-2019 - SITE SPECIFIC REMEDIAL ACTION FILES WITH COMPLETED RODS (PARTIAL SEMS) [PT-412-2022-1016] | 641 | 43 |
| 04/05/2022 | ADMINISTRATIVE RECORD SITE INDEX - SOUTH ANDOVER - REMEDIAL ACTION - UPDATE #6 | 193 | 3 |
| 04/04/2022 | EXPLANATION OF SIGNIFICANT DIFFERENCES [ESD] (SIGNED) - SOUTH ANDOVER SITE | 301 | 4 |
| 03/28/2022 | BRAUN INTERTECH - WORK PLAN AND BUDGET - GROUNDWATER INVESTIGATION - TEMPORARY MONITORING WELL INSTALATION, BUNKER LAKE BLVD NW | 3,048 | 8 |
| 03/02/2022 | EPA LETTER RE: 1,4-DIOXANE AND PFAS IN WELLS IN VICINITY OF SITE | 258 | 2 |
| 02/28/2022 | MPCA LETTER RE: CONCURRENCE WITH EXPLANATION OF SIGNIFICANT DIFFERENCES | 617 | 2 |
| 11/23/2021 | GHD LETTER RE: RESPONSE TO 2021 FIVE YEAR REVIEW REPORT | 271 | 4 |
| 09/22/2021 | FIFTH FIVE YEAR REVIEW REPORT (SIGNED) - SOUTH ANDOVER SITE - 2021 | 7,109 | 45 |

| | | |
|---------|-----------------------------------|------------------------|
| 2003930 | Administrative RecordPublished | UCTL(Uncontrolled) |
| 2003931 | Administrative RecordPublished | UCTL(Uncontrolled) |

| | | |
|------------------------------------|-------|-----|
| GHD - SEPTEMBER 2020 GEOPROBE | | |
| 11/20/2020 INVESTIGATION RESULTS | 8,445 | 143 |
| GHD 2020 GROUNDWATER | | |
| 08/05/2020 INVESTIGATION WORK PLAN | 2,200 | 17 |